



PROBLEM

Solver™ BULLETIN



THE PROBLEM: PREMATURE BALL JOINT WEAR

- Premature ball joint wear is experienced on the Hyundai Accent, Elantra and Tiburon.
- Intrusion and boot failure could accelerate ball joint wear.

THE PROBLEM SOLVER: CARQUEST® BALL JOINT



- Greasable design to reduce friction and flush contaminants.
- Boot with directional grease relief is pressed on for a positive seal.
- Serrated housing accommodates slightly worn control arm housing for easy installation.

PLUS! Features M2 Technology Inside

- Metal stud with full-ball configuration provides 360° of smooth, even, rotational movement for more responsive steering.
- All metal "gusher" bearing design allows lubricant to penetrate bearing surfaces for longer life.
- Exclusive double bearing allows for less pre-load, resulting in reduced steering effort.

YEAR	MAKE/MODEL*	REPLACEMENT PART NO. BALL JOINT
'95-'01	Hyundai Accent	K9455
'95-'01	Hyundai Elantra	K9455
'95-'01	Hyundai Tiburon	K9455

*Check catalog for specific application information.

M2 Technology Design

