

IMPORTANT NOTICE

VEHICLES: 1987-1990 2.8 L. CHEVY BERRETA, CAVALIER
1988-1989 2.8 L. OLDS. CUTLASS, CIERRA, FIRENZA
1988-1989 2.8 L. PONT. GRAND PRIX, TEMPEST
1988-1991 2.3 L. OLDS. CALAIS, PONT. GRAND AM
1989-1990 2.0 L. PONT. SUNBIRD
1991-1992 3.1 L. OLDS. CUTLASS, PONT. SUNBIRD
PROBLEM: HARD PEDAL COMPLAINT, NO RELEASE. BROKEN PRESSURE PLATE
DIAPHRAGM SPRING FINGERS.

SOLUTION: THE ORIGINAL EQUIPMENT BEARING USED ON THE ABOVE VEHICLES
HAD A STEEL SLEEVE THAT CAN RESULT IN HEAVY WEAR OR
SCORING OF THE TRANSMISSION THROW OUT BEARING RETAINER.
THE THROW OUT BEARING SUPPLIED IN THIS KIT HAS A NYLON
SLEEVE THAT ELIMINATES THE SCORING BUT WILL NOT WORK WITH
A THROW OUT BEARING RETAINER THAT IS ALREADY WORN.

*INSTALLING THIS KIT WITH A HEAVILY SCORED, WORN BEARING
RETAINER WILL RESULT IN A NO RELEASE OR A HARD PEDAL
CONDITION. WE STRONGLY RECOMMEND REPLACING THE
THROW OUT BEARING RETAINER (G.M. PART NO. 8672128) AT THE
SAME TIME THAT THIS KIT IS REPLACED.*

WARRANTY: KITS RETURNED FOR WARRANTY MUST HAVE SUPPORTING
EVIDENCE THAT THE THROW OUT BEARING RETAINER WAS
REPLACED OR WARRANTY CONSIDERATION WILL NOT BE GIVEN.

