

**Bulletin CQB 01-08**  
**1999 Buick Century/Regal**

**Subject:** NHTSA Recall Bulletin Anti Lock Brake System ground fault

**Vehicle Involved:** 1999 Buick Century, 1999 Buick Regal

**Condition:** Some of the above-mentioned vehicles, when the ignition key is in the on position, could result in an under hood fire. A condition can occur in which the ABS motor shorts to its case, the ground path is through a flexible brake fluid pipe. As a result from this short, the brake pipe becomes extremely hot. This heat can melt a nearby flexible plastic fuel hose, causing a fire under hood.

**Repair Procedure:** Dealers will install a ground strap from the Electronic Brake Control Module to the body rail located in the engine compartment.

**Campaign number:** 99V170000  
**Number of affected vehicles:** 168,035