

Bulletin CQB 02-08

Subject: Rear Brake Vibration

Vehicle Involved: 2000-2001 Toyota Tundra

Condition: New star wheel adjusters have been developed to reduce the possibility of rear wheel brake vibration. The original star adjusters were designed with 30 teeth. The new design adjuster is now equipped with 26 teeth.

Repair Procedure: Test-drive the vehicle to verify customer's complaint. Inspect rear wheel star adjusters, brakes shoes and measure drums. Replace 30 tooth star adjusters with Toyota part numbers as listed below. If there is uneven brake wear replace rear brake shoes with **CARQUEST part number GD589**. If the rear drums are not within specifications, replace with **CARQUEST part number 3558**.

New design part number

Part name

47061-34010

Star wheel adjuster RH

47062-34010

Star wheel adjuster LH