

Bulletin CQB 02-15

Subject: NHSTA Recall

Vehicle Involved: 1999-2000 Mazda 626
Number of affected Vehicles 71000
Mfg. Campaign No. 89004

Condition: Brake Master Cylinder Reservoir Caps defective. Certain reservoir caps have been found to be defective reducing braking efficiency, increasing the risk of a crash. Some of the caps produced, were manufactured with a worn out die affecting the ventilation holes. Vacuum can result in the reservoir tank pulling the caliper pistons and wheel cylinder pistons back.

Corrective Action: Dealers will inspect the cap and replace it if necessary. Mazda may be contacted at 1-800-222-5500. The National Highway Traffic Safety Administration's Auto Safety Hotline is 1-888-327-4236.