




PROBLEM

Solver

K6449 OFFSET SHAFT GM ASTRO/SAFARI MINI-VAN



PROBLEM:

The inability to reuse the original shaft due to corrosion, or insufficient camber/caster adjustment available to perform wheel alignment and bring the vehicle within specification.



SOLUTION:

The K6449 offset shaft assembly provides an additional 1 1/2° positive camber. If the shaft is being replaced due to corrosion the offset can be compensated for with a shim pack adjustment. The K6449 comes with control arm bushings, and shaft hardware.



APPLICATION:

1995-90 Chevrolet Astro Van (2 wheel drive).
1995-90 GMC Safari Van (2 wheel drive).

PARTS DESIGNED FOR THE PROFESSIONAL

