



**Did you know?**

Incorrect installation of the release bearing is the number one cause of warranty in this kit! Be certain that the fork retainer clips are installed completely inside the bearing collar when mounting the release bearing to the fork.



**----NOTE!!----**

**FAILURE to follow the correct installation will result in a no-release condition, excessive bearing noise and will void your warranty!**