

Bulletin CQB 02-11

Subject: NHSTA Recall Bulletin

Vehicle Involved: 1999-2001 Mitsubishi Montero Sport
Campaign number 01V027000
Mfg. Campaign number 01V027000
Number of affected vehicles 19000

Condition: This bulletin applies to Sport Utility Vehicles equipped with 3.5L engines. These vehicles are equipped with non-compliant brake vacuum hoses. The vehicles do not comply with the requirements of FMVSS No. 106 "Brake Hoses". These vacuum hoses could fail decreasing the braking capability of the vehicle resulting in a crash.

Corrective Action: Dealers will replace the vacuum hose. Customers with questions regarding this recall information may call Mitsubishi at 1-800-222-0037. Also contact the National Highway Traffic Safety Administration's Auto Hot Line at 1-888-327-4236.